

Dear Suppliers,

In order to improve quality and communication, we would like to inform you about the requirements of Pratt & Whitney Rzeszow Purchase Orders.

The documentation delivered to Pratt & Whitney Rzeszow, have to be complete and conforming to drawing, QAD, RCC, SPD, SMD, 150 Instruction, AS9102, ASQR 01 and all other P&WR requirements and specifications called in P&WR POs

Please pay your special attention to fill out correctly the CofC form. All data, which have to be confirmed are listed in 150 instruction point 7.5.1 (Attachment no.5)

e.g.: *ESA requirements*

„ESA process was performed per approved process no, rev. .., level...”

e.g.: *Special processes:*

„Heat Treatment process was performed per CPW21-1”

e.g.: *Non-Destructive Testing (NDT) and NDTCS Certification*

„Non-Destructive Test Control perform by”

(Qualified Source used), when the Supplier is not qualified and he used a qualified source.

e.g.: *3 X-Ray Inspection (RTG) and RACS Certification*

“Radiography Audit Control perform by” (Qualified Source used), when the Supplier is not qualified and he used a qualified source.

It's necessary to confirm part preservation method and its period, if applicable.

If other documents are related to CofC e.g.: raw material certificates, measurement reports, it is necessary to give an attached document number to CofC.

The preferred CofC form is that from Instruction. 150 (Attachment no. 3)- it guarantees the supplier provide all required information per PWR standard.

For parts transferred from USM to VSM, Pratt & Whitney Rzeszow requires a Full FAIR.

Parts with incomplete documentation are quarantined in receiving inspection and in case of lack of response will be claimed.

Delays caused by incomplete or incorrect documentation have a significant impact on the production process and on time delivery of parts to the Customer.