

# Quality Bulletin



Published by Supplier Quality Assurance Department

## Key characteristics measurement and submission requirements

Pratt & Whitney Poland would like to remind about measurement records, submission and monitoring requirements regarding key characteristics KC for products supplied by P&W Poland Suppliers. 01/ESCO instruction invoked on the P&W Poland purchase orders para 8.2.2. e) states the following requirements:

### e) Key characteristic (KC) certification

Supplier shall use UTCQR-09.1 for key characteristic certification.

Supplier shall periodically provide to P&WP QS required documentation, results and analysis for indicated key characteristics.

**For P&WC and P&W end users results of key characteristics measurement shall be provided quarterly.**

UTCQR-09.1 Process Control Requirements specification is available at UTC website at:

<http://www.utc.com/Suppliers/Pages/Aerospace-Supplier-Quality-Requirement-Documents.aspx>

In case of any questions or doubts please use Supplier Request for Information Form 3 (SRFI) to contact with Customer as per Instruction 01/ESCO - Attachment No 1.