

Dear Suppliers,

Recently, several escapes against P&WC marking requirements have been registered. The major problem found is missing P&WC trademark symbol.



P&WC 4-58

P&WC Trademark Symbol

Requirements for this marking is described in SQOP 01-01:

(b) P&WC trademark symbol marking - The organization shall mark all P&WC product with the P&WC trademark symbol as per CPW920 rev. D or subsequent, irrespective of the RSI stated on the P&WC Purchase Order or Schedule Agreement.

Additional explanation can be found in CPW920 (marking application and formats) and SCOP DQR (DQR stamps and application).

All the Suppliers are obliged to perform full containment for this condition: check all the parts in WIP and stores for the Trademark Symbol markings, and introduce corrections according to Pratt & Whitney Canada requirements, if applicable.



