


Analysis of the reasons for rejecting FAI reports

Below is a percentage list of reasons for rejecting FAI reports by P&W Rzeszów, divided into main categories: Form 1, 2 and 3, minimum required documentation and other problems:





On the following pages there is a detailed list of the individual subcategories that make up the main categories (listed above).

Quality Bulletin



Published by Supplier Quality Assurance Department



Quality Bulletin



Published by Supplier Quality Assurance Department

