

Quality Alert

Mistake in Heat Number(Heat Code) on CofC received from supplier.

Problem description:

During quality inspection of part received from a Supplier, it was discovered that Heat Number referenced on CofC was printed with mistake and differed from this which was printed on packing slip. The mistake and a difference in Heat Number printed on these both documents and on part were not discovered by DQCR person performing inspection before shipment from the Supplier.

Remember:

Before shipment of material /parts to Customer always verify if data contained on CofC, packing slip and other documentation attached to a shipment and marking made on material/parts are correct.

Quality Alert