

Dear Suppliers,

In reference to Eagle Eye 20-16 for P&W US drawings we would like to share below clarification on Cage Code marking application according to PWA310.

Part Marking Supplier Code per PWA 310 Revision BJ, Paragraph 5.2.1.3

Paragraph 5.2.1.3 states: "The supplier code shall be located on the item in the vicinity of, and preferably on a separate line beneath the P&W CAGE code marking requirement (5.2.1.8)"

Part Marking MFR Cage Code per PWA 310 Revision BJ, Paragraph 5.2.1.8 Paragraph 5.2.1.8 states: "The CAGE code of the manufacturing activity, prefixed by the letters MFR and a hyphen (-) or dash, shall be marked directly below the P&W CAGE code where space permits".

Above paragraphs define correct sequence of Supplier Code and Cage Code Marking. Producer Cage Code shall be marked directly below P&W Cage Code and Supplier Code shall be marked below both Cage Codes. Example of correct marking:

77445-12345 A Where: 77445 – P&W Cage Code

MFR-ABCD01 12345 A – Part number and revision

67890 MFR-ABCD01 – Producer (Supplier) Cage Code

67890 - Supplier Code

Clarification of statement "the CAGE code of the manufacturing activity".

"Manufacturing activity" shall be considered as company who actually produces given part. In a case when Supplier produces and deliveries parts to P&W Poland, parts shall be marked with Supplier Cage Code, unless otherwise stated on PO.

Omission of Cage Code Marking per PWA310 Revision BJ, Paragraph 5.2.2 d)

If Supplier produces parts for listed in para 5.2.2 d) Engine types, Cage Code Marking is not required.

Note

P&W Poland purchase orders may contain additional part Marking clauses e.g. to mark both Supplier Code and PWR Vendor Code. We ask Suppliers to be cautious during contract review and final inspection. In reference to above information please also note that changes to part marking may require partial FAIR.

In a case of any questions please send your reply to received bulletin email address.

SQA Group of P&W Poland Company



