



GO BEYOND

QUALITY BULLETIN

Published by Pratt & Whitney Company in Poland

Dear Suppliers,

In reference to Eagle Eye 21-3 and below content we ask you to verify production and periodic inspection of castings according to PW-QA 6078 within 10 working days. In a case of discrepancies please contact P&WP QS to establish further action.

To ensure compliance to P&W requirements, the supplier shall have a plan in place that details the method of inspection/verification (e.g., level of sampling inspection, gage method, etc.) for all engineering design and specification requirements including, but not limited to, inspection of all drawing notes, RCC, QAD and PO/SA requirements during production.

As part of the SAE AS9102 approval process, Inspection Acceptance Plans are submitted to the P&W SQAR for review. (Reference FAI -Appendix I: Castings Rev C for guidance)

It is critical that suppliers appropriately define design requirements that would be categorized as periodic and production inspection features. These feature categorizations are often defined by Part Specific Inspection Plan (PSIP) and various PW-QA 6078 Attachments. Any questions concerning categorization of a design requirement should be clarified with the P&W SQAR, P&WP QS or via the SRFI to P&WP.

In addition, P&W requirement revisions including b/p, PW-QA-6078, ASQR-20.1, etc. require detailed review to identify and adjust Inspection Acceptance Plans to meet all P&W requirements.

In a case of any questions please send your reply to received bulletin email address.

SQA Group of P&W Poland Company

No. 99

Export Classification: No technical data

Date: 19 May 2021